# SI-810 Special Version

## Segments

✓ Battery Filling

✓ Textile cone weighment

✓ Coil and wire industries

# Special Features

- Maximum 100 Tare weights
- Optional Buzzer or lamp indication for Logging
- Other standard features for SI-810

# Key Schematic



Display

Bar graph

UNDER   RANGE   OVER

Essaē

| 1 & @ | 2 ABC | 3 DEF | ⏻ |
| 4 GHI | 5 JKL | 6 MNO | →0← |
| 7 PQRS | 8 TUV | 9 WXYZ | →T← |
| ✳ | 0 ↵ + | . | ⊚→ |

SI-810   Max.: 15Kg   e=d$_d$= 1g
Min.: 50g   T= - 7.499kg   (II)

Soft keys

Alphanumeric & Functional keys

MSW #2
( Tare Log )

MSW #1
( Gross Log )

# Display Schematic



1. Soft keys.
2. PLU Name.
3. Total number of logged records.
4. Total number of Tare logged.
5. Max weight.
6. Min weight.
7. Weight status indicators.
8. Weight on platter along with unit of weight.
9. Displaying Load, Date and Time.

# Application

Table mount type (option)

3 2 1

Tare Platform

Filling / Process Station

Gross Platform

Tare

LOG

**SI-810 Filling Machine Series**

**Tank Weigher**

**Barcode and Ink Jet printers Interface**

**Milk Weigher**

**Bag filling**

**Pen Drive Interface and FLP**

## Combo Scale

## Portable Scales

## Check weigher